

Fig. 1





Fig. 2

**Fig. 3**






Fig. 4

**Fig. 5**

**Fig. 6**




Fig. 7

Result	Pre-tilt angle [degree]	
	13.5 μm	7.6 μm
Poor	Up to 2	Up to 4
Slightly poor	2 to 3	4 to 6
Good	3 to 5	6 to 8
Excellent	5 to 10	8 to 10

Fig. 8




Fig. 9





Fig. 10

**Fig. 11**




Fig. 12 Prior Art




Fig. 13 Prior Art




Fig. 14 Prior Art